


### FACTS AND FIGURES



Damage Status - Private Structures

Damage Grade (1-2)  
**123**

Damage Grade (3-5)  
**5,485**

### MAJOR HOUSING TYPOLOGIES

Typology	Municipal	District
Stone and Mud Mortar Masonry	96.59%	90.24%
Brick and Cement Mortar Masonry	1.71%	2.55%
Stone and Cement Mortar Masonry	0.75%	1.23%
Reinforced Cement Concrete (RCC) Frame	0.54%	1.57%
Others	0.41%	4.41%

CBS damage assessment survey, 2015

### HOUSING RECONSTRUCTION & RETROFIT UPDATES

#### Reconstruction Status

Total Eligible HHs	5,749	
PA Agreement	5,578	171
I <sup>st</sup> Tranche received	5,573	176
II <sup>nd</sup> Tranche received	5,345	404
III <sup>rd</sup> Tranche received	4,060	1,689

#### Houses

Under Construction: - Completed: -

#### Retrofitting Status

Total Eligible HHs	34	
PA Agreement	10	24
I <sup>st</sup> Tranche received	10	24
II <sup>nd</sup> Tranche received		34

#### Grievances

Registered: 1,127  
Addressed: 815

#### Non-compliances

Registered: -  
Addressed: -

Data Updated on: 2019-07-30 00:00:00

### PO Presence

Active: No POs Reported

Phased Out: No POs Reported

### STATUS OF CONSTRUCTION MATERIALS

Materials	Unit	Req. Quantity*	Ava.	Cost (NRs.)**
Stone	m <sup>3</sup>	74,256	-	-
Aggregate	m <sup>3</sup>	72,362	-	-
Sand	m <sup>3</sup>	7,893	-	-
Timber	cu. ft.	8,978	-	-
Cement (PPC)	Sack	-	-	-
Cement (OPC)	Sack	240,274	-	-
Rebars	kgs.	810,529	-	-
Tin	bundle	9,813	-	-
Bricks	pcs.	995,738	-	-

#### Types of Workers

1. Skilled mason
2. Labourer

#### Avg. daily wage (NRs.)

-/-  
-/-

### OTHER SECTORS



#### Schools

Damaged: 51  
Under Construction: 32  
Construction Completed: 32



#### Health Posts

Damaged: -  
Under Construction: -  
Construction Completed: -

### KEY CONTACTS

#### Municipal Office

Shrawan Kumar G.C  
Chairman  
9851030336

#### Municipal Office

Ram Hari Thapa  
Focal Person  
9851203284

#### Municipal Office

Laxmi Poudel  
Deputy Chairman  
9851038575

#### DLPIU-GMaLI

Laxam Kumar Seth  
DLPIU-Chief  
9854030525

#### Municipal Office

Bir Bahadur Basnet  
Chief Administration Officer  
9841743662

#### DLPIU-Building

Santosh Kumar Niraula  
DLPIU-Chief  
9851136372

## HHs WITH LAND ISSUES

No Reported Land Issues

## STATUS OF TECHNICAL STAFF


Staff	Available Nos.	Additional Req. Nos.
Engineers	-	-
Sub-Engineers	-	-
Asst. Sub-Engineers	-	-
Masons	- (7 days) - (50 days)	- (7 days) - (50 days)

Source: Municipal survey

## MASON TRAINING


Trainings (# out of total required)

7 days Training



Reached


50 days Vocational Training



Remaining

Source: HRRP Analysis

## TA ACTIVITIES MAP



## FAQs

**Q: What documents are required for enrolment in the GoN housing reconstruction programme?**

A: Two copies of passport size photos and original copy and photocopy of land ownership card and citizenship card. Local officials at the Rural / Urban Municipality will be able to provide information and support and households can enrol at the Rural / Urban Municipality.

**Q: Do we need to pay the engineers when they come to conduct inspections or provide technical assistance?**

A: No, you do not have to pay the engineers, or any other staff, conducting inspections or providing technical assistance. If any field staff request payment for conducting inspection or providing technical assistance you should report it to the Rural / Urban Municipality officials.

For further information 1. Reshma Shrestha (General Coordinator) 9841264190 2. Pradip Sharma (Technical Coordinator) 9851073208 3. Ishor Neupane (Information Management Officer) 9801318265